(*c*) the method adopted for supply of water for the last 15 years (yearwar statement with actual area cultivated may kindly be furnished);

(*d*) the arrangements made for supply of water for the lower atchkatdars;

(*e*) to which atchkatdars water has been supplied for the last three years; (the area cultivated may kindly be furnished);

(*f*) whether there was not a proposal to supply water in block system to the upper as well as the lower atchkatdars every year;

(*g*) the action they have taken about the block system;

(*h*) whether they will adopt this system at least from this year (at present)?

A.—Sri Kadidal MANJAPPA (Minister for Revenue and Public Works).—

(*a*) The atchkat under Hoskote large tank is 2,048 acres and 3 guntas.

(*b*) There are two main channels on either end of the bund and two sluice channels taken from the bund itself.

(*c*) Statement of area cultivated in each year from 1939.—

1. 1939 Full atchkat.
2. 1940 Do
3. 1941 Do
4. 1942 387 acres garden lands.
5. 1943 800 acres Rt. chl. (3 miles).
   800 acres Lt. chl. (3 miles).
6. 1944 Full atchkat.
7. 1945 500 acres.
8. 1946 No irrigation.
9. 1947 Full atchkat.
10. 1948 204 acres below bund sluice.
11. 1949 575 acres—right channel 4 sluices.
    Lt. Chl. 4 sluices and bund sluices.
12. 1950 Full atchkat.
13. 1951 800 acres—Rt. Chl. 12 sluices (2½ miles).
    Lt. Chl. 5 sluices (2) and bund sluices.
14. 1952 1,796 acres up to railway line. The details prior to 1939 are not available.

(*d*) The lower atchkatdars are supplied with water through main channel on either ends of the tank if adequate supply is there.

(*e*) *Vide* reply (*c*) 12, 13 and 14.

(*f*) Proposals for the supply of water in block system to the upper as well as to the lower atchkatdars is under consideration.

(*g*) The proposals are under examination.

(*h*) No.

Amount spent on Repairs and Construction of Tanks in Hoskote Taluk

Q.-592. Srimathi LAKSHMIDEVI RAMANNA (Hoskote-Anekal).—

Will the Government be pleased to state:—

(*a*) the amounts spent on repairs and construction of tanks in Hoskote Taluk during the last five years;

(*b*) the amount spent on each tank?

A.—Sri Kadidal MANJAPPA (Minister for Revenue and Public Works).—

	Year	*Rs.*
(*a*)	1948-49	44,461
	1949-50	32,956
	1950-51	41,617
	1951-52	49,488
	1952-53	30,942
	Total	1,99,464

(*b*) Statement appended on the next pages.

Statement showing the amount spent on construction and repair of tanks during the last five years in Hoskote Taluk.
(SRI KADIDAL MANJAPPA.)

Sl. No.	Name of tank	Amount of estimate	Date of sanction	Amount spent during						Remarks
				1948-49	1949-50	1950-51	1951-52	1952-53	Total	
	18-A—IRRIGATION—ORIGINAL—MAJOR	Rs.		Rs.	Rs.	Rs.	Rs.	Rs.	Rs.	
1	Construction of pipe sluice to Hoskote large tank channels.	16,800	12—45	14,409	..	..	..	..	14,409	Work completed, final bill to be paid.
2	Improving the capacity of Nelavagal Dodkere	14,000	52	744	156	1,926	2,820	1,552	12,298	In progress
3	Improving the right bank channel of Ragimarada ane and channels.	5,000	12—49	..	3,064	1,755	412	..	5,231	Completed
4	Construction of a new tank in S. No. 96 of Bommanhalli village.	10,000	50	..	..	..	1,200	3,559	4,759	In progress
	(a) Desilting of Alur tank	10,000	..	..	..	145	6,018	..	6,163	Completed
	18-A. IRRIGATION—ORIGINAL —MINOR									
5	Reclaiming the water logged area behind Hoskote large tank.	3,550	12—49	..	..	1,267	..	..	1,267	Practically completed
6	Improving the capacity of Ginagara Tank	3,200	9—50	..	..	1,651	369	529	2,549	In progress
7	Improvements to Ginagara tank	1,300	49	576	..	455	..	..	1,031	Completed
8	Constructing silt dam to Nidaghatta tank	1,200	2—50	..	..	593	642	..	1,235	Do
9	Surveying the atchkat of Hosakote large tank	2,000	49	..	198	866	720	502	2,286	In progress
10	Improving the sluice channels of Herosina ane	3,000	2—50	..	871	..	1,349	..	2,220	Practically completed
11	Constructing a super-passage near Kadigehalli tank.	400	3—50	..	..	321	..	..	321	Completed
12	Regarding the channels of Hoskote large tank	4,600	11—51	..	..	2,731	287	41	3,059	Do
13	Remodelling sluice of do ..	3,030	1—51	..	..	572	824	301	1,687	Do
14	Providing locking arrangements to sluice of Hoskote large tank.	3,700	1—51	..	..	..	3,377	549	3,926	Do
15	Breach filling of Bandahalli tank	1,250	2—51	..	..	..	1,182	..	1,182	Do
16	Improvements to Hethakai tank	4,000	3—51	..	..	..	2,292	511	2,803	In progress, final bil be paid.
17	Fixing screw gear rods to Hoskote large tank ..	3,250	7—51	..	..	..	2,250	166	2,416	
18	Constructing a cart bridge to Jimgara tank ..	2,450	7—51	..	..	..	419	106	525	In progress
19	Regrading the channel of Ragimarada ane channels.	1,400	3—52	..	..	..	..	1,287	1,287	Completed
20	Constructing C. I. pipe sluice to Doddaganahalli tank.	3,000	7—51	..	..	..	..	3,107	3,107	Work completed, final bill to be paid.
21	Repairs to waste weir to do ..	1,950	7—51	..	..	..	..	1,670	1,670	Do

	Restoration of Minor Tanks									
22	Jodi Lugumenahalli tank	7,760	10—43	7,000	..	..	2,095	..	9,095	Do
23	Bhandarahosahalli tank	4,990	49	2,000	..	1,803	281	..	4,084	Do
24	Ramalur tank ..	6,150	44	5,000	1,107	..	..	..	6,107	Do
25	Vadigenahalli tank	6,080	49	..	1,500	3,409	479	..	5,388	Nearing completion.
26	Yennappanahalli tank	4,610	49	..	806	2,279	2,511	..	5,605	Completed, final bill to be paid.
27	Kembiganahalli tank	4,982	49		853	168	538	..	1,559	In progress
28	Gorvihalli tank	4,680	49	..	402	341	824	..	1,567	Do
29	Somalpur tank	3,300	6—50	..	..	320	..	..	320	Do
30	Yedagondanahalli tank	3,600	1—51	..	..	..	5,022	..	5,022	Do
31	Ganagulur tank	9,000	42	..	3,802	..	1,305	..	5,107	Work completed, final bill to be paid.
32	Supplemental extension to Lagumenhalli tank	4,150	9—52	..	..	..	..	2,004	2,044	Work in progress
	22-E. Charges									
1	Maintenance work to Mathukere tank ..	1,545	..	813	..	..	..	..	813	In progress
2	Do Palenahalli tank ..	2,234	1—53	110	..	..	..	..	110	Do
3	Do Nandavarthiyelavanakere	2,970	52	1,120	250	..	..	219	1,589	Completed
4	Do Kumunahalli tank ..	5,000	49	1,031	3,675	..	..	296	5,002	Do
5	Do Doddagalliganabbe tank ..	1,700	48	643	..	162	..	1,020	1,907	Do
6	Do Thatnur Chickere ..	1,400	..	..	..	2,233	..	..	2,233	Do
7	Do Medinallasandra tank ..	1,820	49	..	..	1,083		..	1,764	Do
8	Do Doddavallurahalli tank ..	6,000	7—51	..	..	..	..	5,418	5,418	In progress
9	Do Anehalli Ragavanathasandra tank.	1,550	11—51	.. ..	..	..	..	329	329	Do
10	Do Chickere tank	2,150	11—51	..	..	..	..	418	418	Do
	Irrigation Cess Fund Works									
1	Constructing C.I. pipe sluice to Sulebele Chickere	1,200	49	722	636	..	..	..	1,358	Completed
2	Repairs to Bilikere tank	900	49	188	..	..	..	..	188	Do
3	Closing leaks in Honchanahalli tank ..	800	48	442	327	..	..	..	769	Do
4	Repairs to Malenahalli tank	1,860	49	1,123	530	..	..	..	1,653	Do
5	Closing leaks in Pelanahalli tank	280	45	200	..	..	..	..	200	Do
6	Constructing pipe sluice to right channel to Hoskote large tank. ..	600	47	288	..	..	..	..	288	Do
7	Repairs to Devanagundi Doddakere	920	48	619	85	..	..	..	704	Do
8	Repairs to waste weir of Leniur tank ..	1,650	48	418	1,028	..	..	..	1,446	Do
9	Repairs to sluice of Sulebele Chickere ..	1,400	49	722	..	..	..	..	722	Do
10	Pipe acqueduct to Kumbliganahalli tank ..	550	49	269	..	..	..	..	269	Do
11	Repairs to sluice of Somalapur tank ..	540	48	129	359	..	..	..	488	Do
12	Repairs to sluice and waste weir of Solur tank	1,500	49	293	..	..	598	..	891	Do
13	Repairs to Vadigenahalli tank	1,650	48	1,037	..	..	..	..	1,037	Do

(SRI KADIDAL MANJAPPA.) QUESTION NO. 592—*contd.*

Sl. No.	*Name of tank*	*Amount of estimate*	*Date of sanction*	*Amount spent during*						*Remarks*
				1948–49	1949–50	1950–51	1951–52	1952–53	Total	
				Rs.	Rs.	Rs.	Rs.	Rs.	Rs.	
14	Repairs to Honalur tank	1,980	48	1,240	..	..	..	..	1,240	Completed
15	Repairs to waste weir of Thindlu tank ..	2,400	..	1,325	..	..	48	..	1,373	Do
16	Repairs to C.I. pipe sluice to Kallappahalli tank	1,000	49	..	850	..	..	..	850	Do
17	Annual repairs to Hoskote large tank ..	12,000	..	2,000	1,300	2,088	2,657	2,330	10,375	Do
18	Repairs to sluice of Gubbi tank	1,000	49	..	182	335	461	..	978	Do
19	Silt dam in 7/28 of H.M.A. road	70	..	..	70	..	..	..	70	Do
20	Repairs to Doddavanarupahalli tank ..	1,550	..	..	1,474	342	..	..	1,816	Do
21	Closing leaks in Hoskote Chickere tank ..	570	2—50	..	489	49	..	..	538	Do
22	Clearing silt in Hoskote large tank	3,150	..	..	2,880	590	..	1355	4,875	Do
23	Repairs to Mavakere tank Reg. No. 130 ..	1,000	..	..	790	..	..	..	790	Do
24	Repairs to Petanahalli tank	1,750	49	..	1,054	..	..	..	1,054	Do
25	Repairs to Yeragunte tank	1,900	49	..	1,665	..	..	1,665	1,665	Do
26	Improvements to sluice arrangements of Hoskote large tank.	3,900	49	..	135	1,247	..	..	1,382	In progress
27	Pipe acqueduct to Kenobigenahalli tank ..	3,200	49	..	849	..	..	..	849	Do
28	Sluice of Bhoolanahosahalli tank	780	..	..	416	..	..	..	415	Completed
29	Repairs to Muthusandra tank	3,300	50	..	453	2,250	..	..	2,703	Do
30	Repairs to Yelachihalli tank	1,000	48	..	..	1,014	..	..	1,014	Do
31	Closing leaks in Kithaganur tank	400	49	..	..	364	..	..	364	Do
32	Improvements to Doddanallur tank	3,350	..	..	252	1,125	944	..	2,371	Do
33	Breach filling of Hethakki tank	3,200	49	..	449	2,806	..	..	3,255	Do
34	Cleaning silt in Ragimarada ane channels ..	350	50	..	..	327	..	..	327	Do
35	Repairs to sluice of Anehalli Dodkere ..	800	50	..	..	..	715	..	716	Do
36	Constructing pipe acqueduct to Sulebele Chickere. ..	1,900	50	..	..	..	1,115	..	1,115	In progress
37	Repairs to waste weir of Doddaralagere tank ..	3,400	50	..	..	..	2,021	1,118	3,139	Completed
38	C.I. pipe sluice to Pellanahalli tank	2,800	50	..	..	..	224	249	473	In progress
39	Pipe sluice to Alur tank	2,000	50	..	..	..	1,135	..	1,135	Completed
40	Constructing revetment to Emulur tank ..	1,100	50	..	..	..	330	595	925	In progress, final bill to be paid.
41	Urgent repairs to Sulebele tank	930	51	..	..		846	60	906	Completed
42	Closing leaks to Sulebele-Doddakere ..	750	51	..	..	..	107	715	822	Do
43	Repairs to Vagata tank	1,000	48	..	..	..	330	714	1,044	Do
	Total ..			44,461	32,956	41,617	49,488	30,942	1,99,464	

Amount spent on repairs and construction of Tanks in Anekal Taluk.

Q.-593. Srimathi LAKSHMIDEVI RAMANNA (Hoskote-Anekal).—

Will the Government be pleased to state:—

(*a*) the amount spent on repairs and construction of tanks in Anekal Taluk during the last five years;

(*b*) the amount spent on each tank and the years during which spent?

A.—Sri KADIDAL MANJAPPA (Minister for Revenue and Public Works).—

(*a*) Rs. 57,340.

(*b*) Statement appended below.

List of works showing the amount spent on repairs and construction of tanks in Anekal Taluk during the last five years.

Sl. No.	*Names of works*	*Amount of estimate*	*Date of Sanction*	*Amount spent*			
				1948—49	1949—50	1950—51	1951—52
		Rs.		Rs. A. P.	Rs. A. P.	Rs. A. P.	Rs. A. P.
1	Constructing new C.I. pipe sluice to Gavimutt Tank	460	4—50	..	..	363 13 0	62 13 0
2	Constructing a pick-up across Bukkasagara Bandikunte ..	1,210	..	..	..	..	1,159 7 0
3	Constructing a silt dam for halla leading to Hosaravanai Dodkere	900	..	..	..	..	722 2 0
4	Improvements to waste-weir and strengthening the bund of Gavimutt Tank.	480	50—51	..	..	..	502 0 0
5	Repairs to sluice of Byagadadenahalli Tank	850	48—49	..	..	..	466 7 0
6	Repairs to Kodihalla of Cholankere	900	48—49	..	..	386 14 0	174 13 0
7	Repairs to Jigala major tank	700	5/49	..	..	326 7 0	..
8	Repairs to Mutthanallur major tank	2,500	..	..	..	866 9 0	88 8 0
9	Repairs to Neriga Tank	520	50—51	..	..	522 0 0	..
10	Improving Irrigation Channel of Hennagara	2,500	49—50	..	..	..	1,472 2 0
11	Repairs to Bunde Nattasandra Tank	RE. 1,860	50—51	..	1,522 10 0	116 6 0	38 8 0
12	Augmenting Water Supply to Kalkere, Kattimaranakunte ..	1,800	49—50	..	462 15 0	855 14 0	518 1 0
13	Repairs to leaky sluice of Hennagara Tank	5,500	49—50	..	3,867 12 0	239 1 0	570 13 0
14	Repairs to leaky Indhavadi Gowrammanakere	500	..	..	410 12 0	35 0 0	..
15	Repairs to Bommanahalli Ramiahnakere	550	..	..	440 8 0	42 4 0	..
16	Constructing waste-weir to Harohalli Tank	..	..	..	..	649 10 0	281 12 0
17	Repairs to Mathiahnakere of Haroppanahalli	1,500	..	..	..	..	..
		ME.1,271	51—52	..	862 11 0	..	335 10 0

(SRI KADIDAL MANJAPPA.)

QUESTION NO. 593—*contd.*

Sl. No.	*Names of works*	*Amount of estimate*	*Date of sanction*	*Amount spent* 1948—49	1949—50	1950—51	1951—52
		Rs.		Rs. A. P.	Rs. A. P.	Rs. A. P.	Rs. A. P.
18	Urgent repairs to Bund of Cholankatte Heelalige	6,700	48—49	..	..	..	..
		ME. 6,360	51—52	..	4,328 7 0	1,004 1 0	..
19	Constructing silt dam to prevent silt to Nanjapur Katte ..	1,580	..	..	..	1,115 11 0	..
20	Protecting the tank Bund of Bestahamanahalli Tank	400	50—51	..	137 8 0	218 7 0	..
21	Constructing new sluice to Vaderamanchanahalli Tank ..	1,020	..	..	646 13 0	212 0 0	..
22	Constructing waste-weir to Yelachikere of Telagarahalli ..	490	..		351 10 0	131 12 0	..
23	Urgent repairs to leaky sluice of Bommasandra Tank	1,000	..	..	274 11 0	..	..
24	Repairs to sluice, etc., of Vaddarakere of Doddaheggade ..	680	..	..	407 2 0	145 13 0	..
25	Urgent repairs to Rayasandra major tank	1,400	48—49	..	515 3 0	..	..
26	Constructing C.I. Pipe to right sluice of Mayasandra Doddakere..	2,800	..	..	1,228 9 0	168 2 0	..
27	Repairs to sluice and bund of Sarjapur Doddakere	RE. 1,400	..	..	1,206 12 0	283 11 0	..
28	Repairing feeder channel to Anekal Doddakere	1,400	50—51	..	..	1,408 0 0	..
29	Repairs to Sarjapur Chikkere	85	49—50	..	72 12 0	..	..
30	Urgent repairs to Singasandra Mavankere	540	49—50	..	..	260 1 0	..
31	Urgent repairs to silt dam across feeder halla of Billandavadyhalli Tank.	480	50—51	..	..	196 2 0	..
32	Constructing pipe sluice to Mantap tank	1,040	51—52	..	..	371 2 0	..
33	Repairs to sluice and waste-weir of Raghuramiahnakere ..	1,310	..	..	716 7 0	513 5 0	..
34	Strengthening rough stone body wall of Haragadde Urumundinakere	825	..	..	635 10 0	203 14 0	..
35	Urgent repairs to Dommasandra tank	130	50—51	..	..	98 5 0	..
36	Closing leaks of Muttagatti tank	100	50—51	..	..	99 0 0	..
	Total ..	..	..	..	18,088 12 0	10,813 4 0	6,393 0 0
	MAINTENANCE						
1	Maintenance to Telegarahally tank	1,320	12—50	..	..	..	473 14 0
2	Sidhi Hoskote Nanjundiahnakere	750	49—50	..	..	472 3 0	..
3	Sidhi Harohalli Tank	..	..	..	..	353 2 0	126 14 0
4	Sidhi Arehalli tank	4,500	4—50	..	..	2,830 15 0	1,657 0 0
5	Sidhi Mathanallur tank	10,030	49—50	..	..	9,669 7 0	2,290 14 0
	Total ..	..	..	..	..	13,325 11 0	4,548 10 0

RESTORATION

1	Chokkasandra Tank	6,120	..	2,140 6 0	474 3 0	755 0 0	..
2	Solur Marsettykere	3,900	..	..	..	..	4,034 0 0
3	Rachamanahalli Thimmanakere	3,930	..	1,770 6 0	899 13 0	524 14 0	..
4	Halehalli Kodagikere	7,370	..	..	1,378 14 0	2,981 3 0	2,012 4 0
5	Thigal Chowdanahalli Tank	8,000	..	..	..	..	1,056 0 0
6	Nosenur Devarakere	3,460	..	..	1,582 9 0	..	..
7	Chikkaheggade Subbarayankere	6,540	..	1,680 9 0	612 13 0	2,376 8 0	666 11 0
8	Kempavaderahalli Yeerammanakere	4,150	..	991 9 0	488 6 0	1,460 2 0	..
9	Menasinganahalli Gowrammanakere	4,995	..	401 8 0	2,114 13 0	1,279 11 0	..
10	Hoplaghatta Tank	5,500	..	2,794 9 0	442 8 0	527 8 0	..
11	Neralur Doddakere	30,000	..	..	..	525 0 0	5,694 5 0
12	Billapur Tank	5,900	..	2,532 7 0	343 14 0	1,302 11 0	343 10 0
13	Chikkadasarahalli Kodagikere	3,700	..	1,394 4 0	76 7 0	396 4 0	..
14	Soppahalli Tank	9,570	..	..	..	3,864 4 0	1,636 11 0
15	Bhaktipura Gramadkere	10,000	..	..	..	..	363 10 0
16	Konasandra Hongekere	4,950	..	..	..	..	953 4 0
	Total ..	..	..	13,705 10 0	10,880 12 0	15,993 1 0	16,760 7 0

V-, 31 N S2
NS3-9-15-28
(B) 4711